

Home

Interface1

Interface2

Interface3

Interface4

Interface5

Interface6

Axis  
Assignments

Interface  
Settings

Output  
Testing

Tools

# Presets

Create Preset

Reset

Output Type SER

Serial Output

Save

ComPort

COM8

BitsPerSec

9600

Data Bits

8

Parity

None

Stop Bits

1

Output - Bit Range 10

Output - Type ☒ Binary ☐ Decimal ☐ Hex

Startup - Output

ms

H/W Start

Interface - Output

XL&lt;Axis1&gt;CXR&lt;Axis2&gt;C

10

ms

Packet Rate

Shutdown - Output

XECCC

10

ms

H/W Stop